DoDRATTS

- Department of Defense Radiation Testing & Tracking System
- Ensure NRC License Compliance
- AR 710-3, Section II

DoDRATTS Transactions

S - Shipment
R - Receipt
Q - Potential Loss
L - Loss
C/U - Found or Recovered
X - Removal of Source
Y - Installation of Source
W - Wipe Test

DoDRATTS Worksheet

M43A1/CAM WIPE TEST ANALYSIS REQUEST FORM

FROM (complete address):	TO: Rock Island Arsenal ATTN: SIORI-SEM-L (RIA-MSRTL) Rodman Ave., Bldg. 210, RM 407 Rock Island, IL 61299-5000
Surveyor's Name:	Phone (COM/DSN/FAX):
Post/Installation RPO:	Phone (COM,/DSN):
Radionuclide (Circle One): NI63 AM241 Other:	Surveyor's Email:
Device(s) being tested:	Date/Time:
Activity Doing The Wipe (DODAAC):	Reporting Activity (DODAAC):

Sample No.	Owning Unit (DODAAC)	Serial No. of Drift Tube or Cell Assembly	Serial No. of CAM (Z16) or M43A1 (Z03)	TRAN *1	FAIL *2

Note: Indicate all zeros with a slash (⌀).
*1. Transaction Codes (AR 710-3): Wipe Test (W), Removal of source (X), Installation of source (Y).
*2. Place a check mark (X) if failure, i.e., radiac meter indicates a sustained elevated reading above twice background.

Wipe Test Process

- Central Registry

Wipe Test Process

Central Registry

Reporting Activity

Wipe Test Process



Wipe Test Process



Wipe Test Process



Wipe Test Process



Wipe Test Process



Wipe Test Process



Wipe Test Process